

Preconstruction and Post Construction Photographs

Erosion Protection for Pelican Island
GLO Contract No. 09-210-000-3719

See Project Site Plan Sheet 3 of 8 for Photo Station Locations



Photo Station 1 Pre-construction . View east view toward Photo Station 2



Photo Station 1 Post-construction . View east view toward Photo Station 2.
Project revetment section in foreground.



Photo Station 1. Pre-construction. East view . Point of Mustang in far distance with south edge of ship channel to NE.



Photo Station 1. Post-construction . View east down alignment of completed breakwater. Note bank erosion compared to July 2009 photo.



Photo Station 2. Preconstruction. View west toward Photo Station 1



Photo Station 2. Post-construction . View west toward Photo Station 1 (behind revetment section)



Photo Station 2. Preconstruction. View north west toward Corpus Christi Ship Channel . Note position of mangrove in immediate foreground.



Photo Station 2. Post-construction . Note erosion up to mangrove between pre-construction photo and breakwater completion.



Photo Station 2. Preconstruction. View north east to ship in the Corpus Christi Ship Channel and Point of Mustang in far distance .



Photo Station 2. Post-construction . Note erosion between pre-construction photo and post construction.



Photo Station 2. Preconstruction. East view toward Photo Station 3



Photo Station 2. Post-construction . Note erosion between July 2009 photo and breakwater completion. Shoreline nourishment in mid distance .



Photo Station 3. Preconstruction. West view toward Photo Station 2 .



Photo Station 3. Post-construction . Note erosion between July 2009 and project completion. Shoreline nourishment in foreground.



Photo Station 3. Preconstruction. West northwest view toward CC Ship Channel.



Photo Station 3. Post-construction . West end of shoreline nourishment behind completed breakwater section.



Photo Station 3. Preconstruction. View north toward Ship Channel and Redfish Bay, Texas.



Photo Station 3. Post-construction. View north toward Ship Channel and Redfish Bay, Texas with completed breakwater and shoreline nourishment.



Photo Station 3. Preconstruction. View north east along Ship Channel and with Point of Mustang in far center distance.



Photo Station 3. Post-construction. View north east along Ship Channel. Shoreline nourishment and breakwater.



Photo Station 3. Preconstruction. East view. Point of Mustang in far left distance .



Photo Station 3. Post -construction. Shoreline nourishment and breakwater. Note erosion between pre-construction and completion of project.



Photo Station 4. Preconstruction. West view toward Photo Station 3 (behind shrubs on top of bank).



Photo Station 4. Post-construction. View west with shoreline nourishment .



Photo Station 4. Preconstruction. North west view . Camera swinging north to ship channel. Aransas Pass, Texas area in far distance.



Photo Station 4. Post-construction. East portion of shoreline nourishment and completed breakwater.



Photo Station 4. Preconstruction. North view toward CC Ship Channel and Redfish Bay, Texas.



Photo Station 4. Post-construction. Completed breakwater.



Photo Station 4. Preconstruction East north east along CC Ship Channel with ship in distance and Point of Mustang in far center right distance.



Photo Station 4. Post-construction. East portion of completed breakwater.



Photo Station 4. Preconstruction. View east view toward Photo Station 5. Point of Mustang in far left distance.



Photo Station 4. Post-construction. East portion of completed breakwater.



Photo Station 5. Preconstruction . View west toward Photo Station 4.



Photo Station 5. Post-construction. East portion of shoreline nourishment in mid distance and completed breakwater to right.



Photo Station 5. Preconstruction. West north west view toward Photo Station 4 and Ship Channel and Redfish Bay, Texas.



Photo Station 5. Post-construction. East portion of shoreline nourishment and mid to east sections of completed breakwater.



Photo Station 5. Preconstruction. North west view toward and CC Ship Channel and Redfish Bay, Texas. Aransas Pass, Texas areas in far distance.



Photo Station 5. Post-construction. Mid and eastern sections of completed breakwater.



Photo Station 5. Preconstruction. North east view toward and Ship Channel .



Photo Station 5. Post-construction. East end of and completed breakwater, 1 of 2.



Photo Station 5. Post-construction. East end of completed breakwater, 2 of 2.



Miscellaneous Post Construction photo. Typical completed revetment section profile. Looking southwestward along alignment. 10/23/2009



Miscellaneous Post Construction photo. Typical completed breakwater section profile. Looking east along alignment. 10/23/2009.



Miscellaneous Post Construction photo of far east end radial head looking westward behind completed breakwater, 10/23/2009.



FINAL SIGNAGE